

Answer - 1x

No. 02 : CBSE : CFO : BWZ : 2009.

O/o. The Chief Fire Officer  
Bangalore West, Sheshadri Road,  
Highground Fire Station Premises  
Bangalore - 560 009. Dt. 15-01-2009

To,  
Smt. Padmavathy, Chairman,  
Sri Shringeri Sharadadevi Seva Trust,  
Sy. No. 21, Singanayakana Dinne,  
Bagepalli Taluk, Chikkaballapur District

Madam,

Sub: Issue of 'Advice' on requirement of fire prevention, fire fighting & Evacuation measures maintained at Sri Sharada Public School at Sy. No. 21, Singanayakana Dinne, Bagepalli Taluk, Chikkaballapur District. Opinion submitting of.

Ref: Request letter dated: 07-01-2009.

-----<<<<<<>>>>>>-----

With reference to the subject cited above, I wish to state that the premises of Sri Sharada Public School, Sy. No. 21, Singanayakana Dinne, Bagepalli Taluk, Chikkaballapur District was inspected by the Regional Fire Officer, Bangalore North Range on 11-01-2009 with respect to availability & requirement of fire prevention, fire fighting & evacuation measures maintained & required in that Building. The details are as under;

A. Details of the Building: site:-

1. Address of the premises : Shri Sharada Public School, Sy. No. 21, Singanayakana Dinne, Bagepalli Taluk, Chikkaballapur District.
2. Number of building : One Building only.
3. Number of floors : Only having Ground floor .
4. Floor wise details occupancy:-  
Ground floor : 01 Office room, 01 Dining room, 01 Library & 08 Class rooms.
5. Height of the building : 04.60 Mtrs.
6. Site area : 3.40 Acres.

7. Built up area of the Building:-  
Ground floor. : 1,588.40 Sq.Mtrs.
8. Type of construction : Bricks wall with Asbestos sheet roofing.
9. Surroundings:-  
East [ Side ] : Private vacant Land.  
West [ Side ] : Private vacant Land.  
North [ Rear ] : Applicants vacant land.  
South [ Front ] : 10.00 Mtrs wide Baba road.
10. Name and Address of the Building owner : Smt.Padmavathy,Chairman,  
Survey No.21,Singanayakana Dinne,  
Bagepalli Taluk, Chikkaballapur District.
11. Name and address of Applicant : Smt.Padmavathy, Chairman,  
Survey No.21,Singanayakana Dinne,  
Bagepalli Taluk,Chikkaballapur District.
12. Number of students : Students : 250.  
Employees : 16.

B. On inspection of the school premises, the following fire protection, fire fighting and evacuation measures are recommended and they are absolutely essential.

Details	Existing	Recommendations
1. Approach to the premises	The premises is accessible from 10.00 Mtrs wide Baba road located on south side.	The requirement is complied with.
2. Width of open space	East [Side ] : 8.50 Mtrs. West [Side ] : 2.50 Mtrs. North [ Rear ] : 3.00 Mtrs. South [Front ] : 8.00 Mtrs.	The requirement is complied with.
3. <u>Portable Fire Extinguishers :-</u> Ground floor	Not Provided	02 water pr.type extinguishers each of 09 Ltrs. capacity, 02 CO extinguishers of each 01 kgs.capacity shall be provided.



4. Fire Prevention Measures. Not Indicated

1. Explosive & inflammable materials should not be stored in the premises.

2. Accumulation of waste & combustible materials all around the premises shall be avoided.

3. The doors shall not be kept locked during working hours & shall be free from obstructions.

5. Escape routes Not indicated.

Directions in which way students have to move in the event of any emergency should be indicated in the corridor during evacuation. It should be written in luminous point.

6. First Aid Boxes. Not installed.

02 Nos. First Aid Boxes at the ground floor shall be provided near the entrance.

7. Fire orders. Not displayed.

Fire safety plans indicating the details of action to be taken in case of an emergency with tele. numbers of nearest Fire station, Police station & Ambulance etc shall be displayed at the proper places or near the entrance.

8. Training to employees. Not imparted.

At least 40% of staff should be got trained in basic fire fighting at our R.A Mundkur Fire & Emergency Service Academy, Bangalore at an early date.

From the above details it is clear that the 'Management' of Sri Shringeri Sharadadevi Seva Trust, situated at Sy.No.21, Singanayakana Dinne, Bagepalli Taluk, Chikkaballapur District had to install first aid fire extinguishers & yet to display fire safety plans, marking the escape routes, installing first aid boxes & imparting fire training to their employees. Hence with a condition to display fire safety plans (Fire orders), marking of escape routes, installation of first aid Boxes, first aid fire extinguishers & to train atleast 40% of employees in basic fire fighting at our R.A. Mundkur Fire & Emergency Services Academy, Bannerughatta road, Bangalore-29 & maintenance of fire safety & evacuation measures regularly, 'Advice' on requirement of fire prevention, fire fighting & evacuation measures to Sri Shringeri Sharadadevi Seva Trust running a school in the name of Shri Sharada Public school situated at Sy. No.21, Singanayakana Dinne, Bagepalli Taluk, Chikkaballapur District had been issued for a period of one year only.

Yours faithfully



**Chief Fire Officer**

**Bangalore West, Sheshadri Road,  
Highground Fire Station Premises,  
Bangalore - 560 009.**